

SOUTHERN POWER DISTRIBUTION COMPANY OF T.G. LIMITED

TENDER NOTICE NO. 06/2024-25

| Sl | Spec. No | Name of the work | Cost of Specification | Value of Contract | EMD | ROR |
|----|----------|---|-----------------------|-------------------|-------|--------|
| 1 | 1 | Estimate for replacement of LT poles, 11KV poles and DTR's which are damaged in disaster occurred on 31.08.2024 and 01.09.2024 in Narayanpuram and Palannaram villages of Chilkuru Section in Kodad Sub Division in Huzurnagar Division in Suryapet circle.(968000010515) | 500/- | 298655 | 5973 | Others |
| 2 | 2 | Estimate for replacement of LT poles, 11KV poles and DTR's which are damaged in disaster occurred on 31.08.2024 and 01.09.2024 in Redlakunta , Nallabandagudem villages of Kodad Rural Section in Kodad Sub Division in Huzurnagar Division in Suryapet circle.(968000010503) | 500/- | 541720 | 10834 | Others |
| 3 | 3 | Estimate for replacement of 11KV 10Nos and LT 86Nos poles.8Nos DTRs which are damaged in disaster occurred on 31.08.2024 and 01.09.2024 in various villages in Mothey Section at Munagala Sub-Division Huzurnagar Division in Suryapet Circle.(968000010502) | 500/- | 320041 | 6401 | ST |
| 4 | 4 | Estimate for replacement of LT poles, 11KV poles and DTR's which are damaged in disaster occurred on 31.08.2024 and 01.09.2024 in Chilkuru villages of Chilkuru Section in Kodad Sub Division in Huzurnagar Division in Suryapet circle.(968000010507) | 500/- | 235570 | 4711 | Others |
| 5 | 5 | Estimate for replacement of 08Nos 11KV Poles and Nos LT poles. DTRs which are damaged in disaster occurred on 31.08.2024 and 01.09.2024 in various villages in Aanathagiri Section at Munagala Sub-Division Huzurnagar Division in Suryapet Circle.(968000010447) | 500/- | 308432 | 6169 | SC |
| 6 | 6 | Estimate for replacement of LT poles,11KV poles and DTR's which are damaged in disaster occurred on 31.08.2024 and 01.09.2024 in Ganaparam village of Kodad Rural Section in Kodad Sub Division in Huzurnagar Divison.(968000010500) | 500/- | 210321 | 4206 | Others |
| 7 | 7 | Estimate for replacement of LT poles,11KV poles and DTR's which are damaged in disaster occurred on 31.08.2024 and 01.09.2024 in Mogalaikota village of MOTHEY Section.(968000010375) | 500/- | 642322 | 12846 | Others |
| 8 | 8 | Estimate for replacement of LT poles, 11KV poles and DTR's which are damaged in disaster occurred on 31.08.2024 and 01.09.2024 in Lingagiri and Seethampuram villages of Huzurnagar Section in Huzurnagar Sub Division in Huzurnagar Division in Suryapet circle.(968000010508) | 500/- | 411734 | 8235 | Others |
| 9 | 9 | Estimate for replacement of 02Nos 11KV Poles and 55 Nos LT poles. DTRs which are damaged in disaster occurred on 31.08.2024 and 01.09.2024 in various villages in Mattampally Section at Huzurnagar Sub-Division Huzurnagar Division in Suryapet Circle.(968000010441) | 500/- | 332642 | 6653 | Others |

| | | | | | | |
|----|----|---|-------|--------|-------|--------|
| 10 | 10 | Estimate for replacement of 07Nos 11KV Poles and 23Nos LT poles. Which are damaged in disaster occurred on 31.08.2024 and 01.09.2024 in various villages in Mattampally Section at Huzurnagar Sub-Division Huzurnagar Division in Suryapet Circle.(968000010446) | 500/- | 104647 | 2093 | Others |
| 11 | 11 | Estimate is for replacement of 38 poles(8M-24,9.1M-4,Studs-10) 11KV poles and damaged 11KV line near Upender Reddy land 11 Nos 8.0M Poles and 01 No. 9.1 M Pole and 5 Nos stud poles, Konda Laxmaiah Land 3 NOs 8.0 M Poles, Kurra Yellaih Land 03 Nos 9.1 M Poles ,Selam Uppiah land 10 Nos 8Mtr and 05 NOs. Stud poles under 11KV Thummagudem feeder emanating from 33/11KV SS Urulugonda due to heavy wind and gale occurred on 31.08.2024 and 01.09.2024 Mothey Section in Munagala Sub Division in Huzurnagar Division in Suryapet circle.(968000009897) | 500/- | 142988 | 2860 | ST |
| 12 | 12 | Estimate for replacement of 6Nos 33KV poles under 33KV Nalabandagudem feeder emanating from 132/33KV Shanthinagar SS, which were damaged in disaster occurred on 31.08.2024 and 01.09.2024 on Kodad Rural Section in Kodad Sub Division in Huzurnagar Division in Suryapet circle.(968000010506) | 500/- | 100432 | 2009 | Others |
| 13 | 13 | Estimate for replacement of LT poles,11KV poles and DTR's which are damaged in disaster occurred on 31.08.2024 and 01.09.2024 in Gondriyala and Kothagudem thanda villages of Ananthagiri Section.(968000010458) | 500/- | 421023 | 8420 | Others |
| 14 | 14 | Estimate is for Replacement of LT poles and DTR's which are damaged in disaster occurred on 31.08.2024 and 01.09.2024 in Lakkaram village of Ananthagiri Section.(968000010459) | 500/- | 221466 | 4429 | Others |
| 15 | 15 | Estimate for rectification of 33KV Mellachervu feeder and 11KV Thamaram feeder at Nemallipuri colony and Vajinepally village which was damaged due to heavy wind and gale on 31.08.2024 and 01.09.2024 in Chinthalapalem section in Kodad Sub Division in Huzurnagar Division.(968000010529) | 500/- | 110927 | 2219 | SC |
| 16 | 16 | Estimate for replacement of 02Nos 11KV Poles and 30 Nos LT poles. DTRs which are damaged in disaster occurred on 31.08.2024 and 01.09.2024 in Gondriyala villages in Ananthagiri Section at Munagala Sub-Division Huzurnagar Division in Suryapet Circle.(968000010445) | 500/- | 151141 | 3023 | Others |
| 17 | 17 | Estimate for replacement of LT poles, 11KV poles and DTR's which are damaged in disaster occurred on 31.08.2024 and 01.09.2024 in Narsimhapuram,Rangapuram Thanda villages of Mothey Section.(968000010374) | 500/- | 616024 | 12320 | Others |
| 18 | 18 | Estimate for replacement of LT poles,11KV poles and DTR's which are damaged in disaster occurred on 31.08.2024 and 01.09.2024 in Mogalaikota village of Ananthagiri Section.(968000010376) | 500/- | 305976 | 6120 | Others |

| | | | | | | |
|----|----|--|-------|--------|------|--------|
| 19 | 19 | Estimate for replacement of 64Nos LT poles. DTRs which are damaged in disaster occurred on 31.08.2024 and 01.09.2024 in various villages in Mattampally Section at Huzurnagar Sub-Division Huzurnagar Division in Suryapet Circle.(968000010501) | 500/- | 230319 | 4606 | SC |
| 20 | 20 | Estimate for replacement of LT poles, 11KV poles and DTR's which are damaged in disaster occurred on 31.08.2024 and 01.09.2024 in Mangalthadna and Chimiryala villages of Kodad Rural Section in Kodad Sub Division in Huzurnagar Division in Suryapet circle.(968000010519) | 500/- | 264214 | 5284 | Others |
| 21 | 21 | Estimate for replacement of 15Nos LT poles. DTRs which are damaged in disaster occurred on 31.08.2024 and 01.09.2024 in Kuchipudi village in Kodad Rural Section at Kodad Sub-Division Huzurnagar Division in Suryapet Circle.(968000010523) | 500/- | 143892 | 2878 | Others |
| 22 | 22 | Estimate for replacement of 8Nos 11KV Poles and 12 Nos LT poles. 1 No. DTR which are damaged in disaster occurred on 31.08.2024 and 01.09.2024 in Nallabandagudem village in Kodad Rural Section at Kodad Sub-Division Huzurnagar Division in Suryapet Circle.(968000010513) | 500/- | 246774 | 4935 | Others |
| 23 | 23 | Estimate for replacement of LT poles, 11KV poles and DTR's which are damaged in disaster occurred on 31.08.2024 and 01.09.2024 in Gondriyala village of Ananthagiri Section in Munagala Sub Division in Huzurnagar Division in Suryapet circle.(968000010540) | 500/- | 299330 | 5987 | Others |
| 24 | 24 | Estimate for replacement of 12Nos 11KV Poles and 8 Nos LT poles. 1 No. DTR which are damaged in disaster occurred on 31.08.2024 and 01.09.2024 in Thogarrai village in Kodad Rural Section at Kodad Sub-Division Huzurnagar Division in Suryapet Circle.(968000010514) | 500/- | 255168 | 5103 | Others |
| 25 | 25 | Estimate for replacement of LT poles, 11KV poles and DTR's which are damaged in disaster occurred on 31.08.2024 and 01.09.2024 in Betholu and Kondapuram villages of Chilkuru Section in Kodad Sub Division in Huzurnagar Division in Suryapet circle.(968000010530) | 500/- | 136542 | 2731 | SC |
| 26 | 26 | Estimate is for replacement of LT poles,11KV poles and DTR's which are damaged in disaster occurred on 31.08.2024 and 01.09.2024 in Gondriyala villages of Ananthagiri Section.(968000010154) | 500/- | 452566 | 9051 | Others |
| 27 | 27 | Estimate for replacement of LT poles, 11KV poles and DTR's which are damaged in disaster occurred on 31.08.2024 and 01.09.2024 in Chilkuru villages of Chilkuru Section in Kodad Sub Division in Huzurnagar Division in Suryapet circle.(968000010449) | 500/- | 272330 | 5447 | Others |
| 28 | 28 | Estimate is for Erection of new 1.5KM 11KV line for bifurcation of 11kv load form Kistapuram 11kv feeder from kistapuram 33/11kv ss to Thammaram 11kv feeder(T-2432-50-02-22-05-001) | 500/- | 148189 | 2964 | Others |
| 29 | 29 | Estimate for extension of 5Nos. AGL supply each 5HP total 25HP AGL Load to Sri.Avula Jyothi & 4Nos others at Kuchipudi Village, Kodad Mandal in Huzurnagar Division of Suryapet Circle- Under SPA:PE Scheme.(A-0617-50-02-22-02-208) | 500/- | 102999 | 2060 | Others |

1. Tender specifications are to be down loaded from SPDCL website. Two **Separate** Demand Drafts towards cost of specification (Rs.500/-) & bid security @ 2% should be enclosed to the tender.
2. Cost of the tender specification Rs 500.00 should be in the form of DD separate DD drawn in favour of "**Divisional Engineer/Operation/TGSPDCL/Huzurnagar**" on any scheduled bank payable at **Huzurnagar**.
3. The Bid Security @ **2%** of tender value (E.M.D.) mentioned against each specification should be in the form of DD **separately** drawn in favour of "**Divisional Engineer/Operation/TGSPDCL/Huzurnagar**" on any scheduled bank payable at **Huzurnagar**.
4. Bidders claiming for bid security exemption must submit relevant document evidence; other wise the bids shall be rejected.
5. i) Sale of Tender Specifications from website : **16.02.2025**
ii) Last date & time for submission of tenders : **24.02.2025 up to 15.00 Hrs.**
iii) Date & time of Opening of tenders : **24.02.2025 at 16.00 Hrs**
6. The sealed tenders should be deposited in Tender box in our office on or before the above date and time (The tenders should not be sent by post).
7. Tender Specification number, cost DD Rs.500/-, bid security amount DD number must be written on sealed cover.

Cont.....,

8. Once paid will not be refunded under any circumstance.
9. The undersigned reserves the right to reject or cancel any one or all the tender specifications without assigning any reason.


**DIVISIONAL ENGINEER,
OPERATION DIVISION, HUZURNAGAR**